

March 2025

# Glen Earrach Pumped Storage Hydro

## Environmental Impact Assessment Report

Volume 5: Appendices  
Appendix 12.2: Site Photographs

Glen Earrach Energy Ltd

Quality information

Prepared by	Checked by	Verified by	Approved by
Jonathan Shipley	Gillian Scott	Chris Moore	David Lee
	Victoria Deacon		
Associate Heritage Consultant	Technical Director: Built Heritage	Associate Director, Heritage	Technical Director - Renewable Energy
	Principal Environmental Consultant		

Issue History

Issue	Issue date	Details	Authorized	Name	Position
1	March 2025	Submission	DL	David Lee	Technical Director – Renewable Energy

© 2025 AECOM Limited. All Rights Reserved.

This document has been prepared by AECOM Limited (“AECOM”) for sole use of our Client (**Glen Earrach Energy Limited**) in accordance with generally accepted consultancy principles, the budget for fees and the terms of reference agreed between AECOM and the Client. Any information provided by third parties and referred to herein has not been checked or verified by AECOM, unless otherwise expressly stated in the document. No third party may rely upon this document without the prior and express written agreement of AECOM.

## Table of Contents

Photograph 1: View of the Proposed Development from the northeast with the high ground of Meall Fuar-mhonaidh left of centre.....	1
Photograph 2: View from the summit of Meall Fuar-mhonaidh looking to the northeast and the area of the eastern embankments and the access tracks. ....	1
Photograph 3: Loch nam Breac Dearga and the Headpond from the northeast. ....	2
Photograph 4: View of the southwestern end of Loch nam Breac Dearga and the area of the Main Dam.....	2
Photograph 5: View north from Meall Fuar-mhonaidh towards Saddle Dam 1.....	3
Photograph 6: View from Meall Fuar-mhonaidh towards Saddle Dam 2 and the Spillway. ....	3
Photograph 7: View of former peat cutting area (AECOM 010).....	4
Photograph 8: View of forestry access track to be upgraded. ....	4
Photograph 9: View of forestry access track to be upgraded. ....	5
Photograph 10: View of forestry access track to be upgraded. ....	5
Photograph 11: View of previously disturbed ground near the existing hydro scheme on the River Coiltie.....	6
Photograph 12: View of the existing hydro scheme on the River Coiltie with the area of the Workers Accommodation and Temporary Compounds in the distance. ....	6
Photograph 13: View of the area of Temporary Compounds and Temporary Workers Accommodation. ....	7
Photograph 14: View of the area of Temporary Compounds and Temporary Workers Accommodation. ....	7
Photograph 15: View of the area of Temporary Compounds and Temporary Workers Accommodation. ....	8
Photograph 16: View of Cherry Island Crannog (SM9762) from the northern shore of Loch Ness. ....	8
Photograph 17: View of Cherry Island Crannog (SM9762) from the southeast taken from a drone.....	9
Photograph 18: View of Cherry Island Crannog (SM9762) from a drone showing extensive tree cover. ....	9
Photograph 19: View of Cherry Island Crannog (SM9762) from a drone showing the shoreline, as well as the moss covered stone/rubble that appears to form the island.....	10
Photograph 20: View of the Proposed Development from Dun Deardail Forts (SM11884) over Loch Ness towards the Proposed Development. The Headpond is located beyond the high-ground of Meall Fuar-mhonaidh.....	10
Photograph 21: View of the Proposed Development from Dun Deardail Forts (SM11884) over Loch Ness. Dun Scriben Fort (SM6220) is located centre of image in the woodland above the clearing. ....	11
Photograph 22: Ruskich Wood Inn and farmstead (MHG63056) on the north side of the A82. ....	11
Photograph 23: Ruskich Wood Inn and farmstead (MHG63056) on the north side of the A82. ....	12
Photograph 24: Ruskich Wood Inn and farmstead (MHG63056) on the north side of the A82. ....	12
Photograph 25: View of the shoreline on the north side of Urquhart Castle (SM90309) showing the current extent of erosion/disturbance.....	13
Photograph 26: Further evidence of previous disturbance, with geotextile visible in the section/shoreline.....	13
Photograph 27: View of the small former landing area on the eastern side of Urquhart Castle, below the 'Water Gate' showing a wide previously disturbed area now protected by Gabion Baskets.....	14
Photograph 28: Further view of the Gabion Baskets below the 'Water Gate' (facing south) demonstrating existing protection against erosion. ....	14
Photograph 30: Further view of the Gabion Baskets below the 'Water Gate' (facing north) demonstrating existing protection against erosion, as well as the rock outcrop on which most of the castle sits dropping into the loch. ..	15
Photograph 30: View of the southern end of the 'moat' at Urquhart Castle with stone structure and Gabion Basket protection. ....	15



**Photograph 1:** View of the Proposed Development from the northeast with the high ground of Meall Fuar-mhonaidh left of centre.



**Photograph 2:** View from the summit of Meall Fuar-mhonaidh looking to the northeast and the area of the eastern embankments and the access tracks.





**Photograph 3:** Loch nam Breac Dearga and the Headpond from the northeast.



**Photograph 4:** View of the southwestern end of Loch nam Breac Dearga and the area of the Main Dam.





**Photograph 5:** View north from Meall Fuar-mhonaidh towards Saddle Dam 1.



**Photograph 6:** View from Meall Fuar-mhonaidh towards Saddle Dam 2 and the Spillway.





**Photograph 7:** View of former peat cutting area (AECOM 010).




**Photograph 8:** View of forestry access track to be upgraded.





**Photograph 9:** View of forestry access track to be upgraded.



**Photograph 10:** View of forestry access track to be upgraded.





**Photograph 11:** View of previously disturbed ground near the existing hydro scheme on the River Coiltie.



**Photograph 12:** View of the existing hydro scheme on the River Coiltie with the area of the Workers Accommodation and Temporary Compounds in the distance.





**Photograph 13:** View of the area of Temporary Compounds and Temporary Workers Accommodation.



**Photograph 14:** View of the area of Temporary Compounds and Temporary Workers Accommodation.





**Photograph 15:** View of the area of Temporary Compounds and Temporary Workers Accommodation.



**Photograph 16:** View of Cherry Island Crannog (SM9762) from the northern shore of Loch Ness.





**Photograph 17:** View of Cherry Island Crannog (SM9762) from the southeast taken from a drone.



**Photograph 18:** View of Cherry Island Crannog (SM9762) from a drone showing extensive tree cover.





**Photograph 19:** View of Cherry Island Crannog (SM9762) from a drone showing the shoreline, as well as the moss covered stone/rubble that appears to form the island.



**Photograph 20:** View of the Proposed Development from Dun Deardail Forts (SM11884) over Loch Ness towards the Proposed Development. The Headpond is located beyond the high-ground of Meall Fuar-mhonaidh



**Photograph 21:** View of the Proposed Development from Dun Deardail Forts (SM11884) over Loch Ness. Dun Scriben Fort (SM6220) is located centre of image in the woodland above the clearing.



**Photograph 22:** Ruskich Wood Inn and farmstead (MHG63056) on the north side of the A82.





**Photograph 23:** Ruskich Wood Inn and farmstead (MHG63056) on the north side of the A82.



**Photograph 24:** Ruskich Wood Inn and farmstead (MHG63056) on the north side of the A82.





**Photograph 25:** View of the shoreline on the north side of Urquhart Castle (SM90309) showing the current extent of erosion/disturbance.



**Photograph 26:** Further evidence of previous disturbance, with geotextile visible in the section/shoreline.





**Photograph 27:** View of the small former landing area on the eastern side of Urquhart Castle, below the 'Water Gate' showing a wide previously disturbed area now protected by Gabion Baskets.



**Photograph 28:** Further view of the Gabion Baskets below the 'Water Gate' (facing south) demonstrating existing protection against erosion.





**Photograph 29:** Further view of the Gabion Baskets below the 'Water Gate' (facing north) demonstrating existing protection against erosion, as well as the rock outcrop on which most of the castle sits dropping into the loch.



**Photograph 30:** View of the southern end of the 'moat' at Urquhart Castle with stone structure and Gabion Basket protection.



